### AGENDA ITEM FOR ADMINISTRATIVE MEETING

$( \ )$	Discussion	oniy
$(\mathbf{Y})$	Action	

FROM (DEPT/ DIVISION): Dan Lonai, Administrative Services

**PROGRAM:** Building Maintenance

**SUBJECT**: Replace courthouse main roof

The Courthouse roof needs to be replaced. The county can utilize the IMESD/Association of Educational Purchasing Agencies contract for roofing and related services with Weatherproofing Technologies, Inc./Tremco. The company obtained four bids for the replacement of the roof, from Griffith Roofing, Anderson Roofing, Umpqua Roofing and Carlson Roofing, as detailed in the attached estimate. The scope of work includes the total removal of the existing roofing, down to the deck, then seal and install new roofing. The recommendation is to have the lowest bidder provide the services.

## **ACTION REQUESTED:**

Authorize contract through AEPA-025D with Anderson Roofing to replace the courthouse roof for an amount not to exceed \$1,246,640.

ATTACHMENTS: Bid Tabulation	
Date: (04/29/2025) Submitted By: (Dan Lonai)	
********For Internal	Use Only********
Checkoffs:	
( ) Dept. Head (copy)	To be notified of Meeting: Martie McQuain
( ) Human Resources (copy)	
( ) Fiscal	
( ) Legal (copy)	Needed at Meeting:
( ) (Other - List:	
***************	********
Scheduled for meeting on: May 7, 2025	
Action taken:	
**************	********
Follow-up:	

**Umatilla County Roof Replacement Bid Tabulation** 

Price	Concrete Deck Repair sqft	Uplift Strapping plft	Work days	Score
00.800,182,14	00.000	9ZZ-00	2	
\$1,246,640.00	\$35.00	\$21.60	55	
\$1,386,900.00	\$30.00	\$22.00	30	
\$1,427,653.00	\$85.97	\$24.00	06	

# **Umatilla Courthouse**

216 SE Fourth St Pendleton, OR 97801



**Date** Wed 26/03/2025

Job # Roof Cores

Prepared By Max Osborne

## Weather

6:00 AM

52° 🌭

Clear

Wind: 6 MPH | Precipitation: .0" | Humidity: 69%

12:00 PM

72° 🦩

Clear

Wind: 8 MPH | Precipitation: .0" | Humidity: 55%

4:00 PM

81°

Partially cloudy

Wind: 7 MPH | Precipitation: .0" | Humidity: 38%

# **General Notes**

### 1. Penthouse Roof Cores/Pictures

Middle of Roof Core: Fully adhered white single ply 1/4" Gypsum Board 1 1/2" Polyiso Granulated Cap BUR 4 ply BUR Concrete Deck

Side of Roof Core: Fully adhered white single ply 1/4" Gypsum Board 1 1/2" Polyiso Granulated Cap BUR 4 ply BUR Concrete Deck

No tapered package with gutters on all four sides.


































# 2. Cage Roof Cores

Field Core: Fully adhered white single ply Concrete Coating Hard Concrete Deck

**Transition Core:** Adhered white single ply Adhered EPDM High step is Concrete.


Low step has wood blocking with a term bar in the middle.

Field of roof:

- -1/4" gyp -1 1/2" polyiso -granulated cap BUT -4 ply BUR
- lightweight concrete deck

There is yellow fiberglass insulation on the base of the lower wall as well.

Completely saturated with wood block rotting.



3. Wall Core:

Intentionally glued white single ply that is losing adhesion. Concrete parapet wall.

Moisture present on back of membrane and concrete wall.







### 4. HVAC Curb Core

Fully adhered white single ply 1 1/2" Polyiso Metal Curb









## 5. Main Roof Field Cut Out 1 (High side)

2'x2' Cut Out: Fully adhered white single ply 1/4" Gypsum Board 2 layers of 2" Polyiso (With Tapered Package) 3 ply BUR Lightweight Concrete Deck that is 4" deep

In this area there is also a squared off section of hard concrete.














6. Main Roof Field Cut Out 2 (Low side) 20 feet lower on roof level. (You go from 4.5" to 2" of insulation)

2'x2' Cut Out: Fully adhered white single ply 1/4" Gypsum Board 2 layers of 2" Polyiso (With Tapered Package) 3 ply BUR Lightweight Concrete Deck in the entire area 4" deep













I, Max Osborne, have reviewed and completed this report.