

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 12/31/01

CORNER DESIGNATION: 2N33, L-17, the East 1/4 Corner of Section 15.

PREVIOUS RENEWALS/ SURVEYS, ETC.:

Corner was reestablished per Umatilla County Surveyor's Survey Number 93-053-C and the accompanying Corner Record.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap on 1 1/4" galvanized iron pipe with cap buried 14" below ground, marked as shown on monument marking detail. All accessories have been destroyed by construction of the road to the Cultural Institute.

MONUMENT MARKING DETAIL:

T2N R33E
1/4
S15 | S14
1993
PLS 1106

LOCATION & COMMENTS:

Corner falls on East top of bank of the shipping and receiving Road, S 07° E 16' from center of a light pole. Corner is about 250' South of building.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 729510.33
E = 8671740.44

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

\2N33L17

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

RECEIVED BY

Umatilla County Surveyor

Date 2-02

Rec'd by KK

No. 02-47-g