

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 10/02/01

CORNER DESIGNATION: 2N33, R-5, The Southeast Corner of Section 19.

PREVIOUS RENEWALS/ SURVEYS, ETC.:

Corner was remonumented on Record Survey No. 82-50-B.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap, 6" below paved road surface, marked as shown in monument marking detail. There is a 12" spike below road surface, bears S 86°36'40" W., 2.84 feet. There is a 2" iron pipe, (old Redfield reference monument), located 30 feet South and 30 feet West of Corner.

MONUMENT MARKING DETAIL:

T2N R33E
S19 | S20
S30 | S29
1982
PLS 1106

LOCATION & COMMENTS:

Corner is located in approximate centerline of Tutuilla Church Road and Umbarger Lane.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 721313.42
E = 8655965.81

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

2N33R5

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

Umatilla County Surveyor
Date 12-01
By KF
No. 01-211-9