

Index
File No. E-13


CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____ Cor.
No. _____

T 3S R. 33E R.D. Ukiah County _____

Merid. Will. N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Material: Stone Size: 15"x 8"x 7"
Height Above Ground: All
Condition: Good
Markings: Notches

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND - A Douglas fir tree 34" DBH bearing N67 degrees W 28 links distance, has a good scar on it. This is from tree to corner. The tree is very vigorous. Corner is on the east side of the road & can be seen from there. It is about 40' above creek level. Painted a 6" red band around trees and nailed a bearing tree tag as well as a attention sign. Also painted the corner stone red. The rest of the bearing trees are down & rotted mostly away. The whole Pearson Creek drainage looks to have been burned after the

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
corners were set.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By Metal tags
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature MLC Title Forestry Tech Division _____ Headquarters _____ Date 9-12-79 7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor.