

Index

File No. E-17

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or


Survey No. _____

Cor.

No. _____

T 3S R. 33ER.D. Ukiah County _____Merid. Will.N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND -

Material: Stone Size: 12"x 10"x 6"
 Height Above Ground: All
 Condition: Fair
 Markings: Five notches on the South edge

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND - ²
 A 32" Douglas fir that has scribing on the bark, a "N" can be seen but is poor. Only painted this tree as it is a snag about 32 DBH approximately 10' tall & very rotten. Bears $\text{S } 23 \text{ degrees W}$ from the corner. A 21.8" Ponderosa pine bearing N57 degrees W 33 links from the corner has a good scar on it. A pine 32 DBH bearing S 53 degrees E from the corner has a good scar. Both trees - painted a six(6) inch red band around and attached a bearing tree tag on the ~~corner side & an attention sign also was painted red~~. ³

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER.

⁶ corner stone painted red. This is a section corner on the Union ⁷ Umatilla Line.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By Paint & Tags*Signature*

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

MLC c DDH

Title

Forestry Tech.

Division

Headquarters

Date

9/26/79

7100-52-(3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. U.S. G.P.O. 1977-725-576/586

13