

Index
File No. J-9


CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____
Cor.
No. _____

T 3S R. 33E R.D. Ukiah County _____

Merid. Will. N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Material:None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND - A ponderosa pine 20" DBH has been bug killed, bears S35 degrees W 2 links distance. Painted & put only one bearing tree tag on it. Scribing is visible and good. A western larch 19", dead, bearing S57 degrees E 16 lks has a good scar that is over grown. Painted & only put one tag on it, "bearing tree tag". A douglas fir 23" DBH bearing N57 degrees E 33 links has a scar indicating a bearing tree but has been pecked out by woodpeckers as it is very rotten inside. I think ~~this tree has no scribing left inside.~~ Painted a band & the

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

pecked out scar but put no bearing tree tag on it. A western larch 17" DBH bearing N18 degrees w 45 links has visible scribing & is in fair condition. Painted a band & the scribing red. Attached a bearing tree tag to it also.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By Tags & Paint
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature MALC o PDM Title Forestry Tech. Division _____ Headquarters _____ Date 9/28/79 7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. U.S. G.P.O. 1977-725-576/586 13