

Index File No. N-9

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____

T 3S R. 33E R.D. _____ County _____

Merid. Will. N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Material: Stone Size: 14"x 12"x 6"

Height Above Ground: All

Condition: Good

Markings: Painted Stone red NOTCHES

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND - A ponderosa pine 11" DBH for S20 bearing S44 degrees W 31 links. This tree has good scribing visible. A PP 14" DBH for S21 bearing S 59 degrees E 16 links distance has a good scar. A PP 23" DBH for S16 bearing N52 degrees E 150 links distance has a good scar also. All trees I attached a bearing tree tag & an attention sign to. All trees painted with a 6" red band and also painted scars & scribing. This corner is on a SW exposure and very near a rock outcropping. Has an open ridge a 150 feet above it.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By Tags & Paint

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

A p. pine 16" for Section 17 bearing N30W 18 links dist. has a good scar,

Signature
M L C & D D M

Title
Forestry Tech.

Division

Headquarters

Date
10/3/79

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. _____
U.S. G.P.O. 1977-725-576/586