

Exteriors of T. 1 S., R. 37 E., W.M.

Chains	Feet
<p>A tamarack, 20 ins. diam., brs. S.65°W., 17 lks. dist., marked T.1 S., R.36 E., S.1, B.T.</p> <p>A tamarack, 13 ins. diam., brs. S.41°E., 35 lks. dist., marked T.1 S., R.37 E., S.6, B.T.</p> <p>High mountain table land.</p> <p>Soil; gravelly, 2nd rate.</p> <p>Timber; black pine, fir and tamarack.</p> <p style="text-align: right;">Sept. 13, 1881</p>	
General Description.	
<p>This Tp. is very rough, broken and mountainous, except in the S.W. Cor. of the Tps.</p> <p>There may be a few sections of land, suitable for agriculture. The northern part is broken by deep rugged canyons, leading into Meacham Creek.</p> <p>The tops of the ridges on table land, covered with heavy timber of good quality for building and other purposes.</p> <p>There is very little water, except in the deepest canyons. Grass is medium.</p>	
<p>Exteriors of T. 1 S., R. 37 E., W.M. As surveyed by Henry Meldrum, U.S. Deputy Surveyor, Under Contract No. 450, Dated June, 11, 1882.</p>	
<p>Resurvey of West Bdy., as the Cors. on W. Bdy. of this Tp. are not suitable for survey of T.1 S., R.37 E., as it is run from old Cor. to Tps. 1 & 2 S., Rs. 36 & 37 E. I am therefore, compelled to resurvey it. Begin at Closing Cor. to Tps. 1 & 2 S., R. 37 E.</p> <p>A pine, 8 ins. diam., from which;</p> <p>A pine, 7 ins. diam., brs. N.70°E., 40 lks. dist.</p> <p>A pine, 4 ins. diam., brs. S.23°E., 7 lks. dist. and thence I run;</p> <p>N. on W. Bdy. of Sec. 31</p> <p>8.07 The Cor. to Tps. 1 & 2 S., Rs. 36 & 37 E., destroyed mark referring to R.37 E.</p>	