

Found 1/2" Iron Rod Located By Frank Hayes County Surveyor

Replaced With Iron Spike Imbedded in Concrete 2' below Existing Ground Surface 1/2" Iron Pin Flush With Existing Ground at 116

Found Original Rock Corner Identified By County Surveyor



1/2" Iron Pin 3' Below Existing Ground

1/2" Iron Pin 3' Below Existing Ground

1/2" Iron Pin 2' Below Existing Ground

1/2" Iron Pin 2' Below Existing Ground



1/2" Iron Pin 2' Below Existing Ground

Found Original 1/4" Corner Stone Found Iron Spike for 1/4" corner

Replaced with Iron Spike Imbedded in Concrete 2' below Existing Ground



Note

Traverse Intersects South Line of Section 9 10.00' West of Section Corner

THE CITY OF PENDLETON
OFFICE OF THE CITY ENGINEER

SECTION 9
T 2 N R 32 E W M

RECEIVED BY
Umatilla County Surveyor
Date 12-89
Rec'd by XA
No. 89-121-B

DR BY: *Chuck Still*
CK BY: *XA*

SCALE: 1" = 500' DATE: 3-23-54 DRG. NO. B-54-21-M

24-7500