



NOTES:

Bearings are based on observation of Polaris June 19, 1978. See Book 2, Page 146. Solar shots were taken for bearing check for Dead Tie traverse. See traverse detail, Sheet 3 of 3. All bearings and distances shown are true.

All field notes on traverses for Section 12 are in Book 1. Notes used to set brass caps are in Book 2, pages 166-175. Accessory ties for all corners set in Section 12 are described in Certified Record of Land Monumentation.

Computation for all corners set based on Manual of surveying Instruction 1973, Chapter 5. See Book 1, page 187.

LEGAL DESCRIPTION:

U.S. Forest Service ownership; all Section 12, excepting the North half of the Northwest one-quarter and the Northwest one-quarter of the Northeast one-quarter of Section 12, Township 5 South, Range 33 1/2 East of the Willamette Meridian.

I, David H. Krumbain, a registered land surveyor (Engineer) in the State of Oregon, hereby certify that this plot and the notes hereon, or attached, are a correct representation of a survey I performed during May-August, 1978, for the U.S. Forest Service in accordance with the statutes of the State of Oregon and with the Articles of my contract.

David H. Krumbain (s) David H. Krumbain
Registered Land Surveyor
Oregon License No. 933

- denotes U.S. Forest Service Boundary
- denotes Brass Cap
- () denotes G.L.O. record bearings & distance

REGISTERED PROFESSIONAL AND SURVEYOR

DAVID H. KRUMBAIN
JULY 17, 1970
933

Sheet 1 of 3

KRUMBAIN ENGINEERING CO. ENGINEERS - SURVEYORS - PLANNERS 221 S. Main, Pendleton, Oregon	SCALE 1"=500'
	DATE Aug. 1, 1978
Survey for U.S. FOREST SERVICE Section 12, T5S, R33 1/2 E, W.M.	DRN BY TAG
	CKD BY TEH
	ORNG. NO. 78-562