



- ⊙ denotes Brass cap found
- denotes 5/16 in. iron pin with aluminum cap set

**NOTE**

Bearings and section breakdown are based on a survey done by Don Staebler, dated May 20, 1974, Umatilla County Survey Records drawing no. 1-154-C.

Bearings and distances are true.

SE 1/4, SECTION 4, T4N, R28E, W1M.  
1" = 500'

RECEIVED BY  
Umatilla County Surveyor  
Date 3/81  
Rec'd By BLS  
No. S-22A

REGISTERED PROFESSIONAL LAND SURVEYOR  
Terry Hamby  
OREGON  
JULY 14, 1978  
TERRY E. HAMBY  
1638

**KRUMBEIN ENGINEERING CO.**  
ENGINEERS - SURVEYORS - PLANNERS  
221 S. Main, Pendleton, Oregon

Survey for  
**REINHOLD FISCHER**  
NE 1/4, SE 1/4 of Section 4, T4N, R28E, W1M.

SCALE 1" = 100'
DATE Feb 23, 1981
DRN BY M1
CKD BY TEH
DRNG NO. 81-4B

Job No. 81-18  
S-22-A