


- NOTES:
1. The city water is not metered to the lot.
 2. There is no sanitary sewer available.
 3. Electrical Power is available
 4. The ground between the northerly lot line and the Highway is a uniform slope.

POWER POLE (PP/L)
Also End of Line

16" CONC. STORM DRAIN ALIGNMENT NOT STREIGHT

POWER POLE (PP/L)
WITH 2 TRANSFORMERS
NEAR 5431 & 5415
POLE # 0432 - 025043
2) Lines overhang Property
by approx. 2 feet.
3) Also telephone cable
on pole.
4) There is no power easement
Presently for this line



PROJECT: BEELINE LOT SURVEY			
LOT SURVEY FOR BEELINE REFINING CO. IN THE S.E. 1/4 OF SEC. 5 T2N 2N, R32 E.W.M.			
DR. BY: DLS.	DATE: OCT 23, 1964	SCALE: 1" = 20'	
CK. BY:	REV:	SHEET 1 OF 1	
STANLEY G. WALLULIS Consulting Engineer P. O. Box 91 213 S. W. Emigrant Pendleton Oregon			