

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 11/08/01

CORNER DESIGNATION: 2N32, T-21, East 1/4 Corner of Section 26.

PREVIOUS RENEWALS/ SURVEYS, ETC...:

Most recent is Umatilla County Surveyor's Corner Record No. 94-109-C.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap monument 20" below ground in good condition, marked as shown in monument marking detail. Per Corner Record, all accessories are in place except the bearing object tag on 5/8" iron rod in the NE quadrant has been cut in two and all corner information is gone. This Corner has four accessories.

MONUMENT MARKING DETAIL:

T2N R32E
1/4
S26|S25
1994
PLS 1106

LOCATION & COMMENTS:

Corner is located in a farmed field 12 feet West of a North/South fence and 18 feet South of an East running fence.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 718244.26
E = 8645698.30

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

2N32T21

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

RECEIVED BY

Umatilla County Surveyor

Date 12-01

Rec'd by KE

No. 01-210-9