

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 12/31/01

CORNER DESIGNATION: 2N33, N-15, the South 1/4 Corner of Section 15.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Corner was reestablished per Umatilla County Surveyor's Survey Number 93-053-C and the accompanying Corner Record.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap on 1 1/4" galvanized iron pipe with cap buried 12" below ground, marked as shown on monument marking detail. All accessories are intact. The corner has four accessories.

MONUMENT MARKING DETAIL:

T2N R33E
S 15
1/4 -----
S 22
1993
PLS 1106

LOCATION & COMMENTS:

Corner falls at the top of a ditch running East-West. Corner is at the approximate SE corner of the Wildhorse Casino Complex.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 726790.34
E = 8669132.10

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

2N33N15

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

RECEIVED BY

Umatilla County Surveyor

Date 2-02

Rec'd by KK

No. 02-47-9