

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE: 12/31/01**

**CORNER DESIGNATION:** 2N33, N-17, the Northeast Corner of Section 22.

**PREVIOUS RENEWALS/ SURVEYS, ETC.:**

Corner was reestablished per Umatilla County Surveyor's Survey Number 93-053-C and the accompanying Corner Record.

**MONUMENT AND ACCESSORIES FOUND:**

Found a 2 1/2" brass cap on 1 1/4" galvanized iron pipe with cap buried 12" below ground, marked as shown on monument marking detail. Per Corner Record, all accessories are intact. The corner has four accessories.

**MONUMENT MARKING DETAIL:**

T2N R33E  
S15 | S14  
-----  
S22 | S23  
1993  
PLS 1106

**LOCATION & COMMENTS:**

Corner falls on the North side of a ditch with field lines extending North and South.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 726855.12  
E = 8671789.29

**FIRM/AGENCY:** William R. Wells, PLS  
P.O. Box 1696  
Pendleton, Oregon 97801

√2N33N17

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Will. R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6-30-02*

RECEIVED BY

Umatilla County Surveyor

Date 2-02

Rec'd By KE

No. 02-47-9