

OREGON CORNER RESTORATION FORM

Section 5 Township 3N Range 33E

E-7

County Umatilla Date 11-8-85

CORNER DESIGNATION

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out


Previous Renewals/Surveys, etc. \_\_\_\_\_

Krumbein Engineering 1981, County No. S-153-B

Monument(s) & Accessories Found: (Condition and Source)

None

Monument Detail



Monument Set (Procedures and Description)

2 1/2" Brass Cap on 1 1/2" galvanized pipe set at the intersection of  
County roads and set 8" below surface

New Accessories

A fence post by a phone box is Northeast 38.0 feet from Brass Cap; a  
power pole is Northwest 30.10 feet from Brass Cap

Location & Comments

Surveyor's Seal

RECEIVED BY \_\_\_\_\_  
 Umatilla County Surveyor \_\_\_\_\_  
 Date 6-26-86  
 Rec'd By NA  
 No. 86-78-R

Compass Declination \_\_\_\_\_  
 Firm/Agency Krumbein  
 Engineering Ltd.  
 Address 361 SE. Second  
Pendleton, Oregon 98701  
 Party Chief R. Punches  
 Notes \_\_\_\_\_  
 Witness S. Carlson

