

Subdivisional Lines, T. 2 S., R. 32 E., W.M.

Chains		Feet
65.80	Pole and wire fence brs. N. & S.	
82.00	The Cor. to Secs. 29, 30, 31 & 32.	
	Land; mountainous, 82.00 chs.	
	Soil; 4th rate.	
	No timber. Good grass.	
<hr/> General Description. <hr/>		
<p>The part of this Tp., embraced in my contract No. 551, is mountainous and rough. The soil is 4th &amp; 5th grades, and generally, stony.</p>		
<p>Timber of pine, fir &amp; tamarack and cottonwood on N. slopes, and along creeks and canyons.</p>		
<p>There is one settler each in Secs. 19, 27, 29, 30 &amp; 33.</p>		
<p>That portion of Tp., not embraced in my contract, appears to be all occupied, and the settlers and land claimants in this part of the Tp., are very anxious for a re-survey of it, as but a very few Cors. have been found, and they of doubtful origin, and the original notes do not at all apply in <u>any</u> case of subdivisional work with which I am acquainted.</p>		
<p>Notes:</p>		
<p>I took latitude tests, daily, as far as the weather permitted. I built mounds "over" the Cor. stone, instead of "alongside", in such manner as most securely to keep the stone at the true Cor. point, the country being very rough and the surface uneven.</p>		
<p>John G. Arnold, U.S. Deputy Surveyor.</p>		