

T. 4 N., R. 28 E., W.M.

Chains		Feet
	<p>The $\frac{1}{4}$ cor. bet. secs. 3 and 10 and $\frac{1}{4}$ cor. on the N. Bdy. of sec. 3 being intervisible I ran N. $0^{\circ}13'$ E. on line bet. the two above cors. from the $\frac{1}{4}$ cor. bet. secs. 3 and 10.</p>	
10.00	Set flag on line to give direction of N. Bdy. of Farm Unit N.	
17.21	Set 2 x 2 ins. stake on line mkd. W C. as witness cor.	
20.00	Set 2 x 4 ins. stake on line mkd. 1/16 as 1/16 cor.	
20.12	Meandor cor. center O.R. & N. track.	
23.03	Set 2 x 2 ins. stake on line mkd. W.C. as witness cor.	
30.00	Set 2 x 2 ins. stake on line as NW cor. of Farm Unit E.	
40.00	Set 2 x 4 ins. stake on line mkd. 1/16 as center of sec. 3.	
83.26	<p>$\frac{1}{4}$ cor. on N. Bdy. of sec. 3. All of above 1/16 cors. being in thir correct position were not moved.</p>	
	<p>The $\frac{1}{4}$ cor. bet. secs. 2 and 3 and $\frac{1}{4}$ cor. bet. secs. 3 and 4 being intervisible from a point between, I set hub at this point and ran N. $89^{\circ} 57'$ W. on line bet. above points from the $\frac{1}{4}$ cors. bet. secs. 2 & 3.</p>	
20.00	Set trial 1/16 cor. on line.	
30.00	Set trial flag on line to give direction to E. Bdy. of Farm Unit E.	
40.15	Center of sec. 3.	
50.19	Set flag on line to give direction to W. Bdy. of Farm Unit G.	
51.00	Set 2 x 2 ins. stake mkd. W C as witness cor. on line.	
53.00	Meander cor. center O. R & N. track	
55.01	Set 2 x 2 ins. stake mkd. W C as witness cor. on line.	
60.25	Set trial 1/16 cor. on line.	
80.30	<p>$\frac{1}{4}$ cor. bet. secs. 3 and 4. Moved the first 1/16 cor. set on this course to its correct position on line, that is, 20.07 chs. from the $\frac{1}{4}$ cor. bet. secs. 2 and 3.</p>	
	<p>Reset trial flag 10.04 chs. from center of sec. on line. Set 2 x 2 ins. stake as 1/16 cor. in its correct place on line, that is 20.07 chs. from center of section.</p>	