

1st Standard Parallel N., R. 30 E., W.M. (N. Bdy.)

Chains		Feet
	Soil; very poor and sandy, poor grass, Country rolling.	
	W. on S. Bdy. of Sec. 32	
	Var. 18° E.	
40.00	Set post for $\frac{1}{4}$ Sec. cor. in mound of earth, trench & pits as per instructions.	
	Soil; poor and sandy, grass tolerably good. Country rolling.	
	W. on S. Bdy. of Sec. 31	
	Var. 18° E.	
40.00	Set post for $\frac{1}{4}$ Sec. Cor. in mound of earth, trench and pits as per instructions.	
80.00	Set post for cor. to Tp. No. 5 N., of Rs. 29 & 30 E. in mound of earth, trenches and pits as per instructions. Soil; poor and sandy, good bunch grass. Country slightly rolling.	
	E. Bdy. of T. 4, Rgs. 30 & 31 E. W.M. As surveyed by David P. Thompson, U.S. Deputy Surveyors Under Contract No. 81 Dated July 8, 1859.	
	N. bet. Secs. 31 & 36	
	Var. 21° E.	
40.00	Set post for $\frac{1}{4}$ Sec. Cor. and built mound of earth with pits trench etc., as per instructions.	
80.00	Set post for cor. to Secs. 30, 31, 25 & 36, and built mound of earth with pits, trench and etc. as per instructions. Land; level, grass plains Soil; 2nd rate.	
	Aug. 8, 1859	
	N. bet. Secs. 25 & 30	
	Var. 19°30' E.	
40.00	Set post for $\frac{1}{4}$ Sec. Cor. built mound of earth with pits, trench etc., as per instructions.	