

By Request of Ash Pierce Aug 27 1910

J 5 N 629 S W 20 Sec. 19

Chains Links

Commencing at the $\frac{1}{4}$ Sec. corner on West Boundary of Sec 19

Thence East through Cent. Sec 19

40 00 and 60. Old set temporary $\frac{1}{16}$ in stakes80 75 a point 33 lbs south of $\frac{1}{4}$ Sec. corner bet Secs 19 and 20

West bet Secs. 19 and 20

40 00 set stakes $\frac{1}{16}$ Sec cor as I could find no indication of old corner.

80 57 the corner to Sec 19-20-24 & 25-

Thence East on True line

40 25 set post for $\frac{1}{16}$ Sec cor

Thence North through Cent. Sec 19

39 84 True Cent. Sec 19 set 1 x 1 x 15 in Iron pipe

West through Cent. S $\frac{3}{4}$ Sec 1920 12 drive Iron pipe for $\frac{1}{16}$ in40 24 to $\frac{1}{16}$ in in cent. S $\frac{1}{2}$ Sec 19West on true line through Cent S $\frac{1}{2}$ Sec 1920 27 True cor bet Iron pipe for cent S $\frac{1}{2}$ Sec 19

By J. M. W. Winbace County Surveyor
 assisted by Lee Martin and John Luce Chas. H. Chamberlain
 Howard Chamberlain Surveyor