

Henry Hoisinger

March 15 1913

Chains Links

J 5 N B 286 Sec 15-16-22

South bet sec 21 & 22

86 10 The line to sec 21-22-27 & 28

Set on June end

60 72 1/2 set iron pipe for 1/4 mi from west boundary NW 1/4 sec 22

West bet sec 16 & 21

40 11 Set 1/4 sec 22

Set on June end

20 11 set iron pipe for 1/4 mi

West bet sec 15 & 16

40 36 The 1/4 sec 22

Set on June end

10 09 set iron pipe

20 18 " " "

30 27 " " "

40 36 The line to sec 15-16-21 & 22

South through cor SE 1/4 sec 16

10 09 set iron pipe

20 18 " " "

30 27 " " "

East bet sec 15 & 22

81 86 The line to sec 14-15-22 & 23 East on June end

40 93 = 20 46 + 10 23 + 10 23 = to corner

East through cuts 1/2 sec 15

81 00 The 1/4 mi line west on June end 40 50 + 20 25 = 60 75 + 10 12 = 70 87 + 10 13 = 81 00 the line

Beary 16 inchell Co. Survey - by John W. 16 inchell Deputy