

Var	W.	Degres	West	18 Chs	
"	90	"	"	18	
"	87	"	"	7	
"	97	"	"	350	NW Cor Sec 20 To N.R. 22 E.
"	97	"	"	650	
"	102	"	"	13	
"	72	"	"	13	
"	90	"	"	4	Post 13 miles
"	90	"	"	6	
"	83	"	"	10	
"	86	"	"	12	
"	59	"	"	15	
"	62	"	"	16	
"	93	"	"	11	Post 14 miles
"	91	"	"	750	To County Line

J. C. Bramel
Surveyor

