

- on west hill side 30 feet east of point; turn
- N 28° 00' E 10.50 Cross gulch
- 15.97 Set angle stake 30' west of pt on E. hill side; turn
- N 52° 40' E 29.20 " " " " " " " " " "
- N 45° 40' E 39.30 " " " " " " " " " "
- N 9° 40' E 41.90 Parinton Springs gulch - 50; course N. W.; ascend
- 52.60 Ravine - 7'; course W.
- 53.50 Summit
- 62.50 Descend
- 72.00 Ravine, course W. ascend
- 78.50 Summit, descend
- 80.00 Set 2 mile post at point on west side of ridge  
Angle from 2. m. post. descend along summit of ridge
- N 13° 25' E 32.50 Ascend 8'
- 35.97 Summit
- 36.97 Set angle stake 30' W. of pt. on summit of knoll; turn
- N 5° 15' E 38.00 Descend.
- N 5° 15' E 72.20 Intersect gur. Sec. line N 78 through Sec. 6, T 5 N. R 34 E.  
Set angle stake 30' E. of pt. on W. hill side; turn
- N 1° 55' E 75.84 1/4 S. cor. bet. Secs 6 & 31 T 5 N. R. 34 E.
- 78.30 Cross gulch - 100; course N. E. - ascend
- 80.00 Set 3 mile post on line, East hill side.  
Continue course, gur. Sec line N 78 through Sec 31
- 7.00 Summit
- 14.18 Cross fence, course E & W.
- 20.50 Ravine - 6', course N. E.
- 27.50 Summit
- 32.27 Dig & wire fence E & W. Enter wheat field about 25 links west of S. E. corner
- 36.00 Descend
- 51.10 Ravine - 10', course N. E. + ascend
- 54.50 Summit - descend
- 58.50 Leave wheat field & enter pasture
- 80.00 Set 4 mile post a few feet east of point on E. bank of Willow  
Starling's gulch, in stone mound, angles from mile  
post by sun N. 5° W (Var 20° E)
- N 5° 00' W. 20.50 Set angle stake 30' E. of point on W. hill side, turn
- N 6° 00' E 34.70 Ascend 12', from gulch which bears N. E.
- 36.80 Descend
- 38.30 Ravine - 10', course E.