

Acres	Chains	Links
-------	--------	-------

- | | | |
|----|----|---|
| 80 | 06 | The $\frac{1}{4}$ Sec cor bet Secs 29 and 30
Thence East on True line |
| 40 | 03 | Set Stone 10 + 8 + 6 for Center No 29 |
| 80 | 06 | The $\frac{1}{4}$ Sec cor bet Secs 28 and 29
East through Center No 32 |
| 77 | 66 | The $\frac{1}{4}$ Sec cor bet Secs 32 and 33
Thence West on True line |
| 39 | 83 | Set Stone 12 + 8 + 6 for $\frac{1}{16}$ cor in Center No 32 |
| 79 | 66 | The $\frac{1}{4}$ Sec cor bet Secs 31 and 32
West bet Secs 29 and 32 |
| 40 | 00 | Set Temp $\frac{1}{4}$ Sec cor |
| 79 | 72 | a point 52 lls South of Cor to Secs 29-30-31 and 32
Thence S 89° 22' 6" on True line |
| 39 | 86 | Set Stone 12 + 8 + 5 for $\frac{1}{4}$ Sec cor |
| 79 | 72 | The cor to Secs 29-30-31 and 32 |

John W. Kimbell County Surveyor

Assisted by
 Fred Pulse and S. H. Cronk Chairman
 D. H. Nelson Flagman