

Surveyed for Paul Brown and Solley's Mill June 8th 1910

S 1 N 1/2 Sec 20 W 1/4

Chains Links

- Commencing at 1/4 Sec. cor bet Secs. 20 and 29
 thence North on random line through center Sec. 20
 setting True 1/20 corner at 20-40 and 60. chains and at-
 81 00 Intersect north boundary of Sec 20, 56 lls west of 1/4 Sec cor bet Secs 17 & 20
 thence S. 0.24' W on True line
 From N 1/2 cor Sec 20 1/2 run South bet Secs 20 & 21
 40 20 a point 52 lls East of 1/4 Sec cor bet 20 & 21
 N. 0.48' E on True line
 20 10 Set post for 1/4 corner
 40 20 The cor to Sec 16-17-20 & 21
 East through center N 1/2 Sec 20
 40 75 a point 34 lls N of 1/4 cor
 N 89.31' W on True line
 20 30 1/2 Set post for 1/4 cor
 West through 3/2 Sec. 20
 40 07 a point 75 lls South of True center Sec. 20
 S 88.55' E on True line
 20 03 1/2 Set post for 1/4 corner for center 3/2 Sec 20

John W. Kirkbeal County Surveyor
 assisted by Paul Brown and Solley's Mill