

by request of Ed. La Mesa

Feb 12 1911

Chains Links

Sec. 35 T. 5 N. R. 28 E.

East on South Boundary Sec 35

21 00

40 27 the S 1/2 cor Sec 35

North through center S 1/4 Sec 35

20 03 a point 9 lbs west of 1/2 cor

North through center S 1/2 of S 1/4 Sec 35

20 06 a point 10 lbs east of 1/2 cor in center S 1/2 Sec 35

West through center E 1/2 of W 1/2 Sec 35

20 08 center W 1/2 of Sec 35

John W. Winbeck County Surveyor

Survey Record No. 333

Request of F. W. Rowe & August F. Basse Feb. 13 1911

Sec. 26 T. 5 N. R. 28 E.

From center S 1/2 Sec. 26 1/2 mile

North through center

20 00 set 3/4 cor 1/2

60 12 a point 10 lbs west of 1/2 cor in NW 1/4 Sec 23 1/2

East through center Sec 26

10 00 + 2000 40 30 a point 4 lbs North of 1/2 cor

East 1000 - 2000 - 3000 - 40 42 a point 6 lbs South of 1/2 cor

East through center NW 1/4 Sec 26

10 00 - 2000 - 40 24 a point 3 lbs NW of 1/2 cor

John W. Winbeck ^{off.} County Surveyor