

John S. Todd

Feb. 25th 1913

Chains Links

J 2 X 16 986 W M

- from the $\frac{1}{4}$ sec. corner bet Secs 9 & 10 1 run
 West bet Secs 9 & 10
- 20 00 set sign to $\frac{1}{4}$ sec
- 40 01 the corner to Secs 9-10-15 & 16
 West bet Secs 15 & 16
- 40 45 the $\frac{1}{4}$ sec cor bet Secs 15 & 16 three marks on south side
 set 3 iron pipes to cor 9-10-15-16
 set 3 iron pipes to $\frac{1}{4}$ sec
 West bet Secs 9 & 16
- 20 00 set sign to $\frac{1}{4}$ sec
- 40 00 " " $\frac{1}{4}$ sec cor
- 60 00 " " $\frac{1}{16}$ cor
- 81 22 the corner to Secs 6-9-16 & 17 set on same line
 set 3 iron pipes to $\frac{1}{4}$ sec
 set 3 iron pipes to $\frac{1}{4}$ sec
 North bet Secs 16 & 17
- 40 35 set $\frac{1}{4}$ sec cor
 South on same line
- 20 17 set $\frac{1}{4}$ sec
 East along S $\frac{1}{2}$ of Sec. 9
- 81 16 set to corner of Secs 6 & 9
 West on same line
- 20 24 set stake to $\frac{1}{4}$ sec
- 40 58 " " " $\frac{1}{4}$ sec
- 60 97 " " " $\frac{1}{4}$ sec

Gaugy Kimball or person

by John W. Kimball Deputy