

Wellboring Holes by F. S. Wilson

Chains Links

2nd well-

Commencing at the S^W corner of the S^W $\frac{1}{4}$ Sec 16 S 4 N R 35 E W 1
 Thence north 160 rods thence west $91\frac{1}{2}$ rods thence South 160 rods
 thence East $91\frac{1}{2}$ rods to place of beginning and center $91\frac{1}{2}$ rods
 Willie Rice

Commencing at the SW corner of Sec 16 S 4 N R 35 E W 1
 thence East $69\frac{1}{2}$ rods thence north 160 rods thence N 45° 40' W 64 rods to the South boundary
 of the O W R R & N. Co. Right of way thence S 45° 40' W 64 rods thence East 139 $\frac{1}{2}$ rods
 to South boundary Sec. 17 thence East 26 rods to place of beginning $42\frac{1}{2}$ rods
 West tract

Commencing at the SW corner of the S^W $\frac{1}{4}$ Sec 17 S 4 N R 35 E W 1
 thence north 79 $\frac{1}{2}$ rods to the South boundary of O W R R & N. Co. Right of way
 thence S 45° 40' W 187 rods thence South 139 $\frac{1}{2}$ rods to the South line of Sec. 17
 S 4 N R 35 E W 1 thence West 134 rods to place of beginning and center $91\frac{1}{2}$ rods
 John W. Timmes & City C. Sawyer