



LEGEND

- △ Indicates a 5/8" x 30" iron rod with yellow plastic cap stamped A.P.A. set this survey. Replaces monument shown on CS #97-004-A
- Indicates a found 5/8" iron rod per CS#97-004-A

Basis of Bearings

The original monument was a 5/8" iron rod with plastic cap stamped #951.

REGISTERED PROFESSIONAL LAND SURVEYOR
H.M.
 OREGON
 JAN. 21, 1992
 HARMON E. MCLENDON
 2537
 Renew 12/31/98

RECEIVED BY
 Umatilla County Surveyor
 Date 12-97
 Rec'd By KK
 No. 97-254-A

SURVEY NARRATIVE

The monument shown hereon was set to replace the one destroyed during the construction of new streets and sidewalks along West 12th Street and Orchard Avenue. It was reset using ties made during the initial design survey for the improvement project and is in the same position as the original monument.

	REMONUMENTATION SURVEY LOT 5, BLK. D., EKLEBERRY TRACTS SEC 9, T4N, R28E, W.M. HERMISTON, OREGON	FIGURE 1/1
--	--	-----------------------------

97-254-A