

§ 89 E 8 ⁵⁰ / ₁₀₀ chs Angle	§ 55 E 2 ⁵⁰ / ₁₀₀ chs Angle
§ 88 E 53 ch. at Rock Monument 2 ft high.	§ 18 E 16 chs
§ 18 E 12 " to Heppner & Pendleton Road	§ 88 E 15 " Angle on East side of Hill
§ 33 E 4 " 1/4 Sec Cor on South line Sec 21	§ 33 E 18 ⁵⁰ / ₁₀₀ Angle
§ 40 E 7 ⁵⁰ / ₁₀₀	§ 73 E 5 " Mile 41
§ 73 E 5 chs Angle	§ 22 N 8 ⁵⁰ / ₁₀₀
§ 52 E 31 ⁵⁰ / ₁₀₀ on Traveled Road	§ 71 E 7 chs Angle
§ 21 E 28 Mile 42	§ 12 E 18 ⁵⁰ / ₁₀₀ Angle
§ 33 E 48 ⁵⁰ / ₁₀₀	§ 19 E 13 chs Mile 43
§ 19 E 2 ⁵⁰ / ₁₀₀ chs Angle	§ 70 E 36 " Rock Monument Angle
§ 60 E 40 "	§ 74 E 2 ⁵⁰ / ₁₀₀ Mile 44
§ 74 E 30 " Angle	§ 35 E 50 " Mile 45
§ 35 E 18 " "	§ 60 E 22 Angle
§ 49 E 36 " "	§ 10 E 22 Mile 46
§ 10 E 7 " "	§ 26 E 28 Angle
§ 36 E 21 " "	§ 21 E 24 " Mile 47
§ 21 E 5 ⁵⁰ / ₁₀₀ " "	§ 36 E 15 ⁵⁰ / ₁₀₀ Angle
§ 24 E 19 ⁵⁰ / ₁₀₀ " "	§ 16 E 39 ⁵⁰ / ₁₀₀ Mile 48
§ 16 E 9 chs "	§ 25 E 10 chs Angle
§ 27 E 61 " Mile 49	§ 27 E 21 " "
§ 30 E 21 ⁵⁰ / ₁₀₀ " Angle	§ 43 E 13 " "
§ 86 E 16 1/2 " at Summit	§ 61 E 8 " Mile 50 on Summit Mts
§ 69 E 5 chs " on grade on South side of Hill	§ 88 E 8 ⁵⁰ / ₁₀₀ " Angle
§ 23 N 5 " Angle	§ 46 N 13 ⁵⁰ / ₁₀₀ " "
§ 29 N 14 " "	§ 7 N 7 ⁵⁰ / ₁₀₀ " "
§ 48 E 7 ⁵⁰ / ₁₀₀ " descending grade trail	§ 4 N 3 ⁵⁰ / ₁₀₀ " "
§ 20 N 4 ⁵⁰ / ₁₀₀ " "	§ 12 N 5 " "
§ 0 8 " " Rocky side Hill	§ 85 E 2 " Mile 51 Rocky side Hill
§ 85 E 7 ⁵⁰ / ₁₀₀ " " " "	§ 44 E 14 " Angle " " "
§ 61 E 19 " " " " "	§ 54 E 21 " " " "
§ 82 E 5 " " " " "	§ 2 N 5 " " Timber
§ 16 N 4 " " Timber	§ 18 N 14 " Post at end of

Road. Post set. being 51 Miles 49 chs from Coyote to Boots Camp

I hereby certify to the within field notes being correct as per Survey

J. E. Bramel
Surveyor