



HAT ROCK STATE PARK

NOTE:
There is fence line between all monuments.

26.27 AC.

Shea surveyed this parcel in 1975 for Reid. County survey file J-12-AX

NOTE:
In Shea's 1975 survey for Reid he set 1/2" iron rods at the corners. A thorough search of the area of the northerly corner of the Reid parcel found only part of a metal fence post which I assumed to be the corner that Shea set. That point does not fit the state park boundary or the deed distance from the westerly corner but is a compromise.

SURVEY FOR: AL CONFORTH

LOCATION: SW 1/4, SEC. 15, T5N, R29E., W.M. UMATILLA COUNTY, OREGON

DATE: 9-3-80 SCALE: 1"=200'
 ● MONUMENTS FOUND (000) OF RECORD
 ○ 5/8" IRON RODS SET JOB N^o S 8008178

EDWARDS SURVEYING 567-3336 P.O. BOX 763 HERMISTON, OREGON

RECEIVED BY
 Umatilla County Surveyor
 Date 10-80
 Rec'd By BLS
 No. R-170-A
 89

REGISTERED PROFESSIONAL LAND SURVEYOR

G. Dennis Edwards
 OREGON JULY 16, 1971
 G. DENNIS EDWARDS 951

89
 R-170-A