



- denotes Brass Cap found, set in asphalt, stamped by PLS 933, 1981
- denotes iron bar in valve box found, set one foot south of true location. This one foot is shown on the plat of North Milton
- denotes 5/16 in. x 30 in. iron pin set
- denotes 1/2 in. x 24 in. iron pin set
- ( ) denotes Deed record distance

**NOTE**

Used right angles off of DeHaven Street because Deed calls were cardinal directions. Overall measured distance from SE corner of Section 2 to iron bar set in valve box was off from plat distance by 0.10 feet. Distance was shot with AGA 76  
 Front pins are 0.15 feet into sidewalk.

RECEIVED BY  
 Umatilla County Surveyor  
 Date 9-81  
 Rec'd By BLS  
 No. S-118-A

REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR  
*David H. Klein*  
 OREGON  
 JULY 17, 1970  
 DAVID H. KRUMBEIN  
 933

<b>K</b> <b>KRUMBEIN ENGINEERING CO.</b> ENGINEERS - SURVEYORS - PLANNERS 221 S. Main, Pendleton, Oregon	SCALE 1" = 30'
	DATE Sep. 8, 1981
	DRN BY NA
	CKD BY DAK
	DRNG. NO. 81-26B

Survey for  
**PAUL SEAQUIST**  
 located in SE 1/4, SE 1/4, SE 1/4, Section 2, T5N, R35E, W1W1

S-118-A Job No. 81-124