


N  
 SCALE : 1" = 200'  
 DATE : Oct. 1, 1973

**NOTE:**  
 I dug and searched for the 2" steel shaft that was found during the 1967 survey done by Harris for Teribury and I did not find it. The location of the section corner falls in the east ditch of the county road. I set a new man. as shown above, with 2 reference points.



I-42-B

SEC. 34, T1N, R32E,

SURVEY FOR BEN WEINKE TO DRAFT LEGAL DESC. OF OF IRRIGATION DITCH IN SEC. 34, T1N, R32E, W.M.	
SCALE 1"=200'	DATE 10-1-73
DONALD L. STAEBLER CONSULTING ENGINEER P.O. BOX 91 PENDLETON, OREGON	