

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 11/08/01

CORNER DESIGNATION: 2N32, Z-1, the Southwest Corner of Section 31.

PREVIOUS RENEWALS/ SURVEYS, ETC.:

Most recent is Umatilla County Surveyor's Corner Record No. 93-54-C.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap monument flush with ground in small mound of stone approximately 1.0 feet South of fence tee. Cap marked as shown in monument marking detail. Per Corner Record, all accessories are in place. Yellow plastic caps on accessories are burned. This corner has four accessories.

MONUMENT MARKING DETAIL:

T2N
R31E R32E
S36 | S31
S1 | S6
T1N
1993
PLS 1106

LOCATION & COMMENTS:

Corner is located at a fence tee with fences North, East, and West.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 709945.13
E = 8618848.36

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

2N32Z1

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

RECEIVED BY
Umatilla County Surveyor
Date 12-01
Rec'd By KK
No. 01-210-9