

USDA-FOREST SERVICE

Index File No. P-21

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. \_\_\_\_\_ Cor. No. \_\_\_\_\_


T 15 R. 35E

R.D. WALLA WALLA County UMATILLA

Merid. WILL

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

*Corner is just North of Power line clearing.*

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By \_\_\_\_\_  
 Signature \_\_\_\_\_

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_  
 Estab. By \_\_\_\_\_  
 Agency \_\_\_\_\_

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CHAINED SOUTH FROM <sup>14/13</sup>/<sub>23/24</sub> & FOUND TOPOG OF RECORD TO FIT VERY WELL. CORNER POSITION IS IN POWER LINE R/W CLEARING. THIS CORNER MAY HAVE BEEN TIED BY POWER COMPANY SURVEY. CHECK THIS OUT BEFORE PROPORTIONING.

Signature Dennis J. Gaylord

Title \_\_\_\_\_ Division PLS 1636 Headquarters \_\_\_\_\_ Date 6-25-81

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS

A B.T. was found in 1954 by Oregon Highway Division. Coordinates are N 662,520.25 E 540,432.94. SEE MAP C-22

Index File No. T. R. M. Tract or Surv. No. Cor.

P-21