

USDA-FOREST SERVICE

Index
File No. R-24-80

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____

T LS R. 35E R.D. WALLAWALLA County UMATILLA

Merid. WILLAMETTE N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

FND BLM BRASS CAP RISING 5" ABOVE GROUND.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

8" L. PINE BEARS N 10 3/4° E, 38 LKS., 25.0 FT.

B & S E 1/16 80 S24 BT.

7" L. PINE BEARS S 50 1/4° E, 24 LKS., 15.8 FT.,

B & S E 1/16 80 S25 BT.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

SE'LY END OF LONG TANGENT OUT OF MEACHAM ON FREEWAY - YELLOW TAG ON TREE EAST OF HWY, EAST 400' TO E 1/16 CORNER BETWEEN S24 & S25 FOLLOW POST 011 EAST 1/4 MILE ACROSS BUTCHER CREEK TO CORNER ON WESTERLY SLOPE

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

LS 1848

5-85

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

NONE

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

SET STEEL FENCE POST 3 FT. WEST OF CORNER.
ATTACHED SIGNS TO POST & BT'S. PAINTED RED BANDS.

Work Done By B.A. SUTTON Title SURVEYOR Date 5-85 State Registration No. or Agency LS 1848

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No.
R-24-90

T.15

R.35E W.M.

Tract or Surv. No.

Cor. 324
EY680 326