

USDA-FOREST SERVICE

Index File No. A-16

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____


T 1 S R. 36 E

R.D. _____ County UMATILLA

Merid. Will.

N.F. UMATILLA State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

3 1/2" G.L.O. BRASS DISK, SET IN CONC.
FLUSH WITH SURFACE, MKD. →

E 1/6 S3
1984 2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NO. BT'S
A BRASS DISK SET IN CONC. AT E. 1/6 COR. SEC. 34
BEARS S 89° 53' W, 13 LKS.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER LIES ON STEEP, ROCKY, OPEN S.E.
SLOPE, ABOUT 250' N, OF A SHALLOW DRAW,
COURSE N.W.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____

Agency

Signature

Victor McLeod LS

Title

Division

Headquarters

Date

5-1-86

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

SET STEEL POST ABOUT 5 FT. FROM CORNER WITH SIGN 54-9

10

Work Done By V. McLIND Title LS Date 6-4-86 State Registration No. 934
or Agency

Certified Cor. Record Prepared? Yes No Filed At: Date

11

REMARKS

12

Index File No. A-16 T. 15 R. 36 E M. WILL Tract or Surv. No. Cor.

13