

Index
File No. D-8

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____
Cor. No. _____

T 1S R. 36E


R.D. _____ County UMATILLA

Merid. WILL

N.F. UMATILLA State OR.

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND



3 1/2" BLM BRASS DISK SET IN CONC.

SE 1/16 S 5

MKD. AS SHOWN →

1984

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

9" PINE, SCRIBED "SE 1/16 S 5 BT" BEARS S 28 3/4° W, 194 LKS.

12" PINE, SCRIBED "SE 1/16 S 5 BT" BEARS N 21 3/4° E, 174 LKS.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

COR. LIES NEAR TOP OF OPEN, ROCKY RIDGE
S.W. OF A GROVE OF TREES

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature Walter McLeod Title LS

Division _____ Headquarters _____

Date 8-16-85

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Painted RED BAND AROUND BT'S.

ATTACHED SIGN 54-4 TO BACK OF BT'S

SET STEELPOST ABOUT 3 FT. FROM CORNER WITH SIGN 54-9

Work Done By. V. McLIND Title LS Date 6-3-86 State Registration No. 934
or Agency

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. D-8 T. 15 R. 36E M. WILL. Tract or Surv. No. _____ Cor. _____