

Index File No. P-5

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. P 5

Cor. No. 1/4

~~1/4~~
55

T 1 S R. R 36 E

R.D. Pendleton

County Umatilla


Merid. Willamette

N.F. Umatilla

State Oregon

CORNER DIAGRAM

T1S R36E



DESCRIBE CORNER MONUMENT FOUND

Brass cap set summer 1972. See reverse side.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Found a 45" ponderosa pine, live in good condition, with scribing visible.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Established corner position S50°E 66 ft. dist. from bearing tree, found and old mound of stone ~~alongside~~.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
Agency



Signature

Title

Division

Headquarters

Date

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set a 30x2½" iron pipe with brass cap marked as shown, 15" in the ground to solid rock, with "X" chiseled in rock under pipe, for the 1/4 corner between secs. 19 & 20. Raised a 5 ft. x 2 ft. mound of stones around the pipe, from which:

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 14" fir bears N63°E 55 ft. dist. marked T1S R36E S20 BT.
Distance taken to a brass washer in the face of the blaze.
Set a steel fence post approx. 6 ft. North of pipe with "Attention" sign attached.
Used a steel tape and magnetic compass with declination = 20°E/

10

Work Done By D.M. Ferguson Title Land Surveyor Date 7/12/68 State Registration No. 848
or Agency _____
Certified Cor. Record Prepared ? Yes No Filed At: Umatilla Co. Courthouse Date 11/16/72

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. 13