


LAND CORNER RECORD

(Rectangular)

1. T 1S R 36E No. X9 Cor. 1/4 Mer. W State Ore N. F. Umatilla Dist. Pend. 75

2. Corner Status



3. Original Description \_\_\_\_\_ Vol. ? Page 642 Where Recorded BLM Portland

4. Description of Corners: Post 3' long 3" square 24" in ground marked 1/4 S on W face, from which a tam. 9" dia. bears S50°E 9 lks marked 1/4 S B.T., a tam 7" dia bears N50°E 13 lks marked 1/4S B.T.

5. Investigation Notes:

From tag on Summit Rd. & by compass & pacing we found two tam trees that fit the above description however no legible markings were found on either tree.

7. Photo Identification

Photo No. \_\_\_\_\_

Ident. By: \_\_\_\_\_

8. Plane Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Field Book No. \_\_\_\_\_

Where Filled \_\_\_\_\_

9. Evaluation

Authentic \_\_\_\_\_

Needs Verif. \_\_\_\_\_ Monument NO

Re-estab. \_\_\_\_\_ Survey X

Land Status private



6. Signed R. C. Holmes Title Engineering Asst Date 7-23-62

PERPETUATION RECORD

10. Monument:

11. Accessories

Field Book \_\_\_\_\_ Page \_\_\_\_\_

12. Set By \_\_\_\_\_ Title \_\_\_\_\_  
License \_\_\_\_\_ Agency \_\_\_\_\_ Date \_\_\_\_\_

13. Recorded By \_\_\_\_\_ Volume \_\_\_\_\_ Page \_\_\_\_\_  
(Agency) \_\_\_\_\_  
(Date) \_\_\_\_\_ (City) \_\_\_\_\_ (County) \_\_\_\_\_ (State) \_\_\_\_\_

14. Remarks: