

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 10/30/01

CORNER DESIGNATION: 2N32, C-1., the West 1/4 Corner of Section 6.

PREVIOUS RENEWALS/ SURVEYS, ETC.:

Most current is Umatilla County Surveyor's Corner Record No. 88-19-C.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap 2" above ground level in small mound of stones, in North/South fence line, monument marked as shown in monument marking detail.

As per Corner Record, both accessories exist and are in good condition. Corner has only two accessories.

MONUMENT MARKING DETAIL:

T2N
R31E | R32E
1 | 4
S1 | S6
1988
PLS 1106

LOCATION & COMMENTS:

From old Dump Road take new road to Level 3 building, continue through gate, 1/2 mile to fence corner and monument.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 738846.18
E = 8618329.83

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

*Found
2N32C1
A. Neuman*

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

RECEIVED BY

Umatilla County Surveyor

Date 12-01

Rec'd By JK

No. 01-210-9

05
26
05