

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 12/31/01

CORNER DESIGNATION: 2N32, G-17, The East 1/4 Corner of Section 10.


PREVIOUS RENEWALS/ SURVEYS, ETC..:

Corner was reestablished under Umatilla County Surveyor's Corner Record No. 90-50-C and accompanying Record of Survey.

MONUMENT AND ACCESSORIES FOUND:

Found a 3" brass disk in top of West curb of Southwest 2nd Street. Cap is marked as shown in monument marking detail. As per Corner Record accessories are O.K. except the NW accessory is missing and the railroad spike is paved over at the intersection of SW 2nd Street and SW Hailey Avenue. The witness corner originally had four accessories.

MONUMENT MARKING DETAIL:



LOCATION & COMMENTS:

Witness corner located on West curb of SW 2nd Street.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

For true corner point: N = 734035.32	For witness mon. 87.72' NE: N = 734095.24
E = 8640026.00	E = 8640090.04

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

05
26
05

2N32G17
Karen A. Norman

90

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 06-30-02

RECEIVED BY
Umatilla County Surveyor
Date 2-02
Rec'd By KK
No. 02-46-A