

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 12/31/01

CORNER DESIGNATION: 2N32, J-13, the Northeast Corner of Section 16.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Corner was most recently maintained under Umatilla County Surveyor's Corner Record No. 90-50-C and accompanying Record of Survey.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap monument on galvanized iron pipe, cap 6" above ground, marked as shown in monument marking detail. As per Corner Record accessories are intact. Corner has four accessories.

MONUMENT MARKING DETAIL:

T2N R32E
9 | 10

16 | 15
1988
PLS 933

LOCATION & COMMENTS:

Corner located East of Kube Car Wash, near Wendys, on the West side of Olney Cemetery.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 731209.44
E = 8634884.86

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

2N32J13

From R. Norman

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

rchews 06-30-02

RECEIVED BY

Umatilla County Surveyor

Date 2-02

Rec'd By KE

No. 02-46-9

05
26
05