

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE:** 11/15/01

**CORNER DESIGNATION:** 2N32, V-25, The Southeast corner of Section 25 only.

**PREVIOUS RENEWALS/ SURVEYS, ETC..:**

Most current is Umatilla County Surveyor's Corner Record No. 94-109-C.

**MONUMENT AND ACCESSORIES FOUND:**

Found a 2 1/2" brass cap monument 12" below gravel road surface, marked as shown in monument marking diagram.

All accessories are intact per recorded Corner Record. The corner has four accessories.

**MONUMENT MARKING DETAIL:**

T2N  
R32E R33E  
S25 | S31  
S36 |  
1994  
PLS 1106

**LOCATION & COMMENTS:**

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 715713.07

E = 8651024.78

**FIRM/AGENCY:** William R. Wells, PLS  
P.O. Box 1696  
Pendleton, Oregon 97801

\2N32V25

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6-30-02*

RECEIVED BY

Umatilla County Surveyor

Date 12-01

Rec'd by JK

No. 01-210-9