

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE: 10/08/01**

**CORNER DESIGNATION: 2N32V9, The Northeast Corner of Section 32.**

**PREVIOUS RENEWALS/ SURVEYS, ETC..:**

Umatilla County Surveyors Corner Record: 94-109-C.

**MONUMENT AND ACCESSORIES FOUND:**

Found 2 1/2" brass cap on galvanized iron pipe monument with cap buried 12" below ground in good condition, marked as shown in monument marking detail. Per corner record, all accessories are intact.

**MONUMENT MARKING DETAIL:**

T2N R32E  
S29 | S28  
S32 | S33  
1994  
PLS 1106

**LOCATION & COMMENTS:**

Corner is located approximately 15 East of East right of way fence for Birch Creek Road in CRP field.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 715317.97  
E = 8629945.28

**FIRM/AGENCY:** William R. Wells, PLS  
P.O. Box 1696  
Pendleton, Oregon 97801

2N32V9

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6-30-02*

RECEIVED BY

Umatilla County Surveyors

Date 2-02

Received by KK

No. 02-4349