

OREGON CORNER RESTORATION FORM

Section 9 Township 2N Range 33E

County UMATILLA Date JULY 13, 1989

9-12

CORNER DESIGNATION

C-E 1/16 SEC 9  
G-12

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. \_\_\_\_\_

I-177-A, M 49 B

Monument(s) & Accessories Found: (Condition and Source)

ACTUAL CORNER NOT IN, BIA BRASS CAP S 00° 57'13" E. 30.00 FT.

Monument Detail



Sketch



Monument Set (Procedures and Description)

SET P.K. NAIL AS TEMPORARY CORNER, WILL BE REMONUMENTED AFTER CONSTRUCTION UNDER A SEPARATE CONTRACT

New Accessories

NONE

Location & Comments

NEW RECORD OF SURVEY Compass Declination \_\_\_\_\_

FOR UIR 8(1) Firm/Agency \_\_\_\_\_

MISSION HIGHWAY WHITE SHIELD, INC.

Address P.O. BOX 477

RECEIVED BY GRANDVIEW, WA 98930

Umatilla County Surveyor Party Chief MICHAEL LEJEUNE

Date 9-89 Notes \_\_\_\_\_

Rec'd by JA Witness THOMAS BAKER

No. 89-98-B

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*R. David Schurian*

OREGON  
JUNE, 1976  
R. DAVID SCHURIAN  
1060