

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE:** 01/11/02

**CORNER DESIGNATION:** 2N33J25, The Northeast Corner of Section 13.

**PREVIOUS RENEWALS/ SURVEYS, ETC.:**

See Umatilla County Surveyors recorded survey: 91-70-B.

**MONUMENT AND ACCESSORIES FOUND:**

Found railroad spike 2" below road surface in a 4-way intersection of Niktyoway and Cayuse Road.

**MONUMENT MARKING DETAIL:**

**LOCATION & COMMENTS:**

Located in 4-way intersection of Niktyoway and Cayuse Road.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 732399.35

E = 8682303.64

**FIRM/AGENCY:** William R. Wells, PLS  
P.O. Box 1696  
Pendleton, Oregon 97801

2N33J25

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*RENEWALS 6-30-02*

**RECEIVED BY**

Umatilla County Surveyors

Date 2-02

Rec'd by KK

No. 02-43-9

✓