

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 01/23/02

CORNER DESIGNATION: 2N33J3, The North Quarter Corner of Section 18.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Most recent Umatilla County Surveyors recorded corner record: Q-14.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass disk in concrete, flush with ground, marked as shown in monument marking detail. There is a highway paddle stamped 1/4 S7

S18, Southwest of corner, 1.5 feet.

MONUMENT MARKING DETAIL:

STATE HWY DEPT

1 S7
4 S18
1969

LOCATION & COMMENTS:

Located in triangle between highway off ramp (West) and highway on ramp (East). North of overpass bridge.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 731888.68
E = 8653087.66

FIRM/AGENCY: William R. Wells
P.O. Box 1696
Pendleton, Oregon 97801

2N33J3

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

RECEIVED BY

Umatilla County Surveyor

Date 2-02

Rec'd by KK

No. 02-43-9

✓