

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 03/07/02

CORNER DESIGNATION: 2N33Z13, The Southeast Corner of Section 33.

PREVIOUS RENEWALS/ SURVEYS, ETC.:

Monument tied and noted on survey record: 98-232-B.

MONUMENT AND ACCESSORIES FOUND:

Found a nail with bottle cap and flagging tied around it in intersection of Best and South Market Road.

No visible accessories.

MONUMENT MARKING DETAIL:

LOCATION & COMMENTS:

Located at intersection of Best and South Market Road.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 710781.14

E = 8666874.49

FIRM/AGENCY: William R. Wells
P.O. Box 1696
Pendleton, Oregon 97801

2N33Z13

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1917
WILLIAM R. WELLS
1106

renews 6/30/02

RECEIVED BY

Umatilla County Surveyor

Date 5-02

Rec'd By KK

No. 02-128-9