

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE:** 12/20/01

**CORNER DESIGNATION:** 2N33G25, The East Quarter Corner of Section 12.

**PREVIOUS RENEWALS/ SURVEYS, ETC.:**

Most recent Umatilla County Surveyors recorded survey: 99-164-B.

**MONUMENT AND ACCESSORIES FOUND:**

Found 1 1/2" aluminum cap on 5/8" rebar set in 3" pipe filled with concrete, buried approximately 1 foot below West edge of gravel road, approximately 8 feet East of fence corner. No visible accessories, marked as shown in monument marking detail.

**MONUMENT MARKING DETAIL:**

EAST 1/4 COR SEC 12  
LS 1861

**LOCATION & COMMENTS:**

Approximately 1 foot below West edge of gravel road, approximately 8 feet East of fence corner.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 735050.39  
E = 8682234.02

**FIRM/AGENCY:** William R. Wells, PLS  
P.O. Box 1696  
Pendleton, Oregon 97801

2N33G25

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6-20-02*

**RECEIVED BY**

Umatilla County Surveyors

Date 2-02

Rec'd By KK

No. 02-43-9